



City of WOODSTOCK

Department of Building & Zoning

121 West Calhoun Street
Woodstock, Illinois 60098

phone 815.338.4305
fax 815.334.2267
bandzdept@woodstockil.gov
www.woodstockil.gov

Cross-Connection (Backflow Prevention) Device Inspection Fees

<u>Size</u>	<u>Insp Fee</u>	<u>Re-Insp Fee</u>	<u>Add'l Device Fee</u>	<u>2nd Re-Insp Fee</u>
1" or less	\$75.00	No Charge	\$50.00	\$75.00
1 1/4" or greater	\$100.00	No Charge	\$75.00	\$100.00

Charges are per address. If you own more than one property with different address numbers, your inspections for each address will start with the initial inspection fee and any additional devices at the same address at the additional device fee.

For more than one device at an address: the largest device will be charged at the regular inspection fee and any additional devices will be charged at the additional device fee.

A failed device must be repaired by a qualified plumber and the City will re-inspect once at no charge to you. If a device needs to be retested more than once the fee reverts back to the initial inspection fee charge. The City of Woodstock does not make repairs on failed devices; the City allows 21 days to repair a failed device.

Properly functioning devices are vital to the quality of our potable water system for all Woodstock residents. Title 35 of the Administrative Code adopted by the City of Woodstock, requires that the City ensure Backflow Prevention Devices are in proper working order to protect the potable water supply for all residents of the municipality. Failure to provide documentation of Backflow Prevention Device inspections could result in significant fines from the Illinois Environmental Protection Agency (IEPA) or other regulatory agencies.